



March 1, 2024

**Subject: Supply Disruption – BONDERITE® S-ST 5351 AERO and BONDERITE® S-ST 5351 THIN AERO**

Dear Valued Customer:

The ability of Henkel Corporation (“Henkel”) to procure a raw material used in the production of certain Henkel products has been limited due to the supplier’s inability to supply such material. Henkel is currently unable to predict the duration of this disruption, and, as a result, there may be delays in deliveries of the following products (“Products”).

Product IDH	Product Description
596971	BONDERITE S-ST 5351 AERO
597167	BONDERITE S-ST 5351 AERO
377809	BONDERITE S-ST 5351 AERO
377813	BONDERITE S-ST 5351 AERO
597313	BONDERITE S-ST 5351 THIN AERO

We are in the process of reviewing our ability to fill existing orders and will need additional time to confirm recent orders.

Henkel is in close contact with its suppliers and using all commercially reasonable means to leverage its global supply chain to address this situation and support its customers.

Your account manager will contact you to discuss the status of current and future orders. Henkel appreciates your patience and understanding during this challenging period.

With Best Regards,

*Jake Vlacich*

Henkel Corporation  
Regional Product Manager

DOCL#330