



May 2, 2022

**Subject: Supply Disruption Impacting LOCTITE® AERO Products: Epoxy Curing Agent**

Dear Valued Customer:

The ability of Henkel Corporation (“Henkel”) to procure an epoxy curing agent raw material used in the production of certain LOCTITE® AERO products has been limited due to capacity constraints at the raw material manufacturer. Henkel is in the process of reviewing its ability to fill existing orders for the products listed in Attachment A hereto, and will need additional time to confirm orders. As a result, you may experience a delay in your deliveries.

Henkel is in close contact with its supplier and using all commercially reasonable means to leverage its global supply chain to address this situation and support its customers. Your account manager will contact you to discuss the status of current and future orders.

Henkel appreciates your patience and understanding during this challenging period.

Sincerely,

A handwritten signature in black ink that reads "George Thomas". The signature is written in a cursive style with a horizontal line underneath the name.

George Thomas  
VP Regional SBU Head of Industrials Americas  
Henkel Corporation

Attachment A: Impacted Product List

## Attachment A

### **Impacted Product List**

LOCTITE EA 9359.3  
LOCTITE EA 9360  
LOCTITE EA 9364FR  
LOCTITE EA 9377  
LOCTITE EA 9392  
LOCTITE EA 9394  
LOCTITE EA 9394.2  
LOCTITE EA 9394.3  
LOCTITE EA 9394.4  
LOCTITE EA 9394S  
LOCTITE EA 9395  
LOCTITE EA 9396  
LOCTITE EA 9396.6MD